


WIRING DIAGRAM

6 7 8 9 10 11 12



Note: SW=Switching

OPTION

No	Function	Open	Short
A	% Break	61%	67%
B	Pulse	N	10:1
C	Flash Time	B C E	
D		1 1 1	700ms
		1 1 0	600ms
		1 0 1	450ms
		1 0 0	110ms
		0 1 1	250ms
E		0 1 0	90ms
		0 0 1	300ms
		0 0 0	
F	Redial Time	E F	
G		1 1	15
		1 0	10
N	Test Program	0 1 4	
		0 0 1	
		0 0 0	
O	DTMF Test	Dual	Single
P	Full one touch	O	X

1 Short
0 Open